Scarf Caught In Drill Causes Asphyxiation

An employee at a mine was found strangled to death. The scarf he was wearing around his neck had become twisted around the rotating drill.

To prevent such a tragedy from recurring, remember these safe work practices. Loose clothing and jewelry should never be worn around moving or rotating equipment. Drills and all machinery must be stopped before being inspected or worked on.