

# Power Press Safety Infographic



# DANGER

## CLOSING RAM AND DIE

**Do not operate this machine until you read and understand the following safety precautions.**

**NEVER** operate this machine unless you have been fully trained and have received and understand all operating instructions.

**NEVER** place any part of your body in the die area.

**NEVER** place any part of your body where it can be struck or crushed by part movement.

**NEVER** operate this machine without the use of a point-of-operation safeguard that will protect you from injury.

**NEVER** work on this machine unless power is off, the flywheel is at rest, safety blocks are used between the dies, and all energy (electrical, air, hydraulic, etc.) is in a zero state.

**ALWAYS** use hand tools for feeding and retrieving material from the point of operation or any other hazardous part of the machine.

**You are exposed to moving machine parts that can crush, dismember, and cause death.**

**Never place your hands or any part of your body in this machine.**



**DO NOT REMOVE OR COVER THIS WARNING!**

WasteStickers.com 800-331-0061 WS6X9115

Source: <https://rockfordsystems.com>