

Construction Company Cited for Alleged Willful Violation Issued \$70,000 in Proposed Fines

An OSHA inspection found that a worker was exposed to a potential fall of 50 feet from a roof as a result of working without fall protection. OSHA requires that an effective form of fall protection be used whenever work is being conducted at heights of six feet or more.

[*Shawnlee Construction Inc., Plainville, MA. Release number 09-213-BOS/BOS 2009-053, March 4, 2009*]