It Was Only a Matter of Time Picture This



What is wrong in this picture?

On many occasions it is only a matter of time before an incident

or fatality occurs and, in this situation, it is probably expected to happen. There are two workers working at heights without any proper PPE and the air conditioner in which they are standing will not last long.

Falls are the leading cause of fatal accidents in the Ontario construction industry, and even the incidents that do not result in a worker fatality have dire consequences that are life changing for the injured worker, and financially stressful for the employer. To help both employers and employees reduce the risk of a workplace fall injury with safety practices and procedures.