Overhead Hazards Fatality Report

INCIDENT

A comparison in real time between a Near-Miss/Close Call and a fatality.

See a video online in which workers in Rio de Janeiro are repairing the 125-foot-high Christ the Redeemer statue after it was struck by lightning. In the video, the workers are tied off but are using a hammer and chisel that are not tied off and below is a crowd of people. In the middle of the video, one of the workers answers a call from his son on his cell phone, which also is not tied off.

In another example, a man delivering sheet rock to a construction site in Jersey City was killed by a tape measure. The independent contractor for a trucking company was leaning into a car window to speak with someone and when he pulled his head out, he was struck by a one-pound tape measure that had slipped out of a worker's hands 50 stories above.

Needless to say, if that worker on the statue in Rio de Janeiro had dropped his hammer and it had hit a visitor below, it likely would have caused a fatality.

Download to read more...