

Picture This! A Hand on the Bucket Rope is Worth Two on the Ladder



Picture This nearly always focuses on unsafe work practices, but this week we have a photograph showing workers doing the right thing. In this case, a worker is shown using a bucket and rope to hoist tools to an elevated work area. This arrangement allows workers to maintain three points of contact when ascending or descending ladders. (eLCOSH)